

1. Footpath issues:

FP/BW	Comment	Location	Status
FP 4	Landowner diversion signed, but no DMMO... ESCC aware, but 2 previous RDC PA diversions have complicated situation since not correctly actioned. Very low footfall	Netherfield	No need for further action, at present
FP 13	RR/2015/2981/P Condition 3 appealed and over-ridden	Foxhole Farm	No further action
FP 18	Ramblers have queried* path route and width through Beech Farm – the OS map does not accord with the ESCC on-line Definitive map which appears to be wrong? (*Report: <i>BAT_20171217_01_FP18_Report</i>)	Beech Farm	ESCC RoW team response awaited
FP 52 FP 58	RR/2017/2539/P: Impact on FP 58 and 52 – planning condition requested	Off Marley Lane	Situation being monitored by Ramblers
FP 57	Concern about large pile of rubble, near to new barn, across correct line of FP	Off Marley Lane	Situation being monitored by Ramblers
FP 73	Deeply rutted – almost impassable track through Burnt Chimney Farm Electric fence obstructions... ESCC RoW team aware and working with tenant farmer – but very slow progress	East of Great Wood	Situation being monitored by Ramblers and ESCC
FP 82	Lower Almonry Farm track to south-east corner of Recreation Ground at Mansers Shaw – all year round muddy: needs surface improvement Was bid for Community Help, but no action undertaken	Off North Trade Road	Further BTC action (Community Help) requested
<i>Not a PRow</i> BW 86b	Mansers Shaw – BTC supported path is not a PRow: Very narrow bridge from FP82 crossing gill is too narrow and requires a handrail for minimum safety acceptability. Then path should be designated a Permissive Path, at the least Surface damaged due to farming operations, severely “poached/muddy”, high footfall all year round – needs repair in several places, back to hard surface, with improved drainage Reported* to Environment Committee on 2017-10-03 (*Report: <i>BAT_20171018_02_BW88_v2_Report</i>)	Off North Trade Road BTC owned land off Park Lane (parallel with “Long Plantation”)	Further BTC action requested Further BTC action requested

...continued overleaf

FP/BW	Comment	Location	Status
BW 86ab	Wooden pedestrian gate closer damaged Reported* to Environment Committee on 2017-10-03 (*Report: <i>BAT_20171018_02_BW88_v2_Report</i>)	End of Park Lane on BTC owned land	Further BTC action requested
FP 87	3-part project to improve urban path utility, promoted by Battle Ramblers: 1. ESCC to install new wooden kissing gate (paid by BR) in place of broken stile – To be done 2. Hard surface segment between gill and steps 3. BTC to improve surface on northern slope of gill	South of B&L school	Parts 2 and 3 Completed Awaiting ESCC supplier delivery
BW 88b / FP 95	"1066 Country Walk" Major engraved Finger Post rotting damage – needs replacement	BTC owned land	Further action required
FP 107	Mountjoy – Windmill – all year round muddy: needs surface improvement Was bid for Community Help, but no action undertaken	Off Mountjoy	Further BTC action (Community Help) requested
Linking BW 109g BW 67b	New footway between Harrier Lane and Great Wood entrance is required for 1066 Country Walk continuity – bid for this project to ESCC is in the Battle area report by Sustrans BTC is represented by Bev MARKS in the ESCC Cycling & Walking Forum which provides advice on small projects needs Route recently raised by Environment Committee in connection with Heritage Trail – not recommendable, at present, without a footway	Southside of Marley Lane	Further follow-up/lobbying action required/meeting with Sustrans suggested?

...continued overleaf

2. Planning Applications with/and FP/Footway issues

	Comment	Location	Status
RR/2016/725/P RR/2017/1136/P	Lillybank Farm development – Outline and reserved matters approved conditional Footways/cycleways conditions requested s106 agreement: see sch3/Part 2/para 1b Potential CiL payments to BTC...	A 2100, London Road	Further BTC action requested: Related to A2100 footway improvement
Steps2Ramps	BLAPG project – detailed report to BTC P&T Committee by Alan Cole on 2017-12-12 Possibility of funding towards Steps2Ramps project?	Bowmans Drive - Mountjoy	Plan-development being monitored BTC/ESCC meeting to be arranged
RR/2017/1259/P	Tollgates – Outline approved conditional Footways/cycleways conditions requested but rejected in Officers report... Potential s106 agreement... Potential CiL payments to BTC...	Off Tollgates	Situation being monitored
Battle Schools Greenway	BLAPG project - to provide off-road route	Claverham College to Abbey Gatehouse	Plan-development being monitored
Battle Health Pathway	BLAPG project – detailed reporting to BTC Environment Committee	North Trade Road Recreation Ground	Plan-development being monitored

Bev MARKS
2018-January-02